


METASYS INTRACOMFORT	
© 9 □ ➡	
ADDRESS	I ▼)LINKS
INTRACOMFORT	CURRENT CONDITIONS FLOOR 4 WEST WING 08/15/00 10:11 AM
☐ CURRENT CONDITIONS ☐ TEMPERATURE FEEDBACK	INDOOR OUTDOOR 70.3 °F 80.9 °F
HUMIDITY FEEDBACK	56.0 %RH 66.1 %RH
☐ AIR QUALITY FEEDBACK	AREA NOTICES THE WEST WING AIR CONDITIONING
SUBMIT COMMENT	WILL BE SHUT DOWN NEXT WEEKEND FOR MAINTENANCE
TURN ON LIGHTS	
☐ IDENTIFICATION	GENERAL NOTICES
☐ HELP	




- 29


FIG. 3


FIG. 2


- 29

















		C	COMPLAINT LOG	90-		•		
DATE & TIME	COMFORT	COMPLAINT	OCCUPANT ID	AREA TEMP.	YTIQIMUH	C02	SETPOINT	DISCHARGE TEMP.
08/15/00 1:45 P	08/15/00 1:45 PM FLOOR 4 WEST	НОТ	BAKER, J.	79.0 °F		60% RH 500 PPM	76.0 °F	€0.0 °F
08/15/00 1:40 P	08/15/00 1:40 PM FLOOR 3 EAST	COOL	POND, J.	68.2 °F	1 1	62% RH 461 PPM	7° 0.27	55.0 °F
08/15/00 9:46 A	08/15/00 9:46 AM FLOOR 1 LOBBY	НОТ	THOMAS,K.	∃ _o 9.08	60% RH	450 PPM	4° 0.27	51.0 °F
08/15/00 9:30 P	08/15/00 9:30 PM FLOOR 3 EAST	HUMID	RADLER, D. 73.9 °F	73.9 oF		76% RH 475 PPM	74.0 ºF	54.0 °F
08/14/00 4:46 P	08/14/00 4:46 PM FLOOR 4 WEST	НОТ	BAKER, J.	78.8 °F	57% RH	488 PPM	4° 0.97	55.0 °F
08/14/00 2:16 P	08/14/00 2:16 PM FLOOR 2 NORTH	T000	FOX, A.	70.07	61% RH	463 PPM	Jo 0.9∠	55.0 °F
08/14/00 9:23 P	08/14/00 9:23 PM FLOOR 1 EAST	DRAFTY	SWIFT, C.	72.9 °F	56% RH 495 PPM	495 PPM	73.0 ºF	51.0 °F

FIG. 8